


## Republic of the Philippines

## Department of Education

Region IV-A
SCHOOLS DIVISION OF QUEZON PROVINCE



10 June 2024

DIVISION MEMORANDUM DM No. 461, s. 2024

# REITERATION ON POLICIES AND GUIDELINES IN PROMOTING SAFETY AND WELL-BEING OF LEARNERS WITHIN SCHOOL PREMISES

TO: Assistant Schools Division Superintendents

**Division Chiefs** 

Public Schools District Supervisor

Public Elementary and Secondary School Heads District DRRM and School DRRM Coordinators

All Other Concerned

- 1. In reference to Regional Memorandum No. 379, s.2024 titled Reiteration of Policies and Guidelines in Promoting Safety and Well-Being of Learners Within School Premises, all School Heads and the School DRRM Team are advised to implement all the preventive and safety measures to ensure hazard free and child friendly environment in school under the MATATAG Agenda aligned with our Division KALILAYAN Project.
- 2. Please see attached Regional Memorandum for details..
- 3. Immediate and widest dissemination of this Memorandum are highly desired.

ROMMEL C. BAUTISTA, CESO V Schools Division Superintenden

drrmapr06/10/2024

DEPEDQUEZON-TM-SDS-04-010-005


























27 May 2024

### Regional Memorandum

No.379 s.2024

## REITERATION OF POLICIES AND GUIDELINES IN PROMOTING SAFETY AND WELL-BEING OF LEARNERS WITHIN SCHOOL PREMISES

#### To: Schools Division Superintendents

- In reference to the MATATAG Agenda of the Department of Education, this Office, through the Education Support Services Division reiterates one of the strategic directions to take good care of learners by promoting learner wellbeing, inclusive education, and a positive learning environment.
- Relative to this, the Schools Division Offices shall promote the implementation of programs, projects, and activities that address disaster preparedness and mitigation in schools in compliance with DepEd Order No. 37, s. 20151.
- The School Governance and Operations Division through Division Engineers or deployed Engineers and Architects under Contract of Service and Disaster Risk Reduction and Management focal person shall provide technical assistance to the schools in assessing the safety of school buildings and other facilities and providing school safety plan.
- School heads shall be instructed to encourage learners to identify and address hazards and risks as mandated by DepEd Order No. 23, s. 20152.
- Enclosed is the recommended Hazard Mapping template for quarterly 5. submission of schools to the Schools Division Offices, starting June 30, 2024.
- For more information or queries, please contact Chief Eduarda M. Zapanta, 6. Engr. Jamaica Rose G. Rolloque or Wilbert C. Ulpindo of Education Support Services Division at (02) 8682 - 2114 local 430.

Immediate dissemination and compliance with this Memorandum are highly 7. desired.

ATTY. ALBERTO T. ESCOBARTE, CESO II

Regional Director

DOWNLOADED Date/Time: MAY 2 9 2024

Chicke 12:29 M

03/ROE6







Email Address: region4a@deped.gov.ph

Website: depedcalabarzon.ph



By:

Ref. No.

<sup>&</sup>lt;sup>1</sup> The Comprehensive Disaster Risk Reduction and Management (DRRM) in Education Framework <sup>2</sup> Student-Led School Watching and Hazard Mapping

SCHOOL WATCHING CHECKLIST (Reference: Annex A of DO 23, s. 2015)					
School Name:			ם	ate when the survey is	
		<u></u>		onducted late Submitted to SDOs	-
School ID:		<u> </u>		ate Submitted to SDOs	$\dashv$
CI	Broken window	N .	£3	Broken/dilapidated ceiling	Ì
C	Slippery pathway		Π	Open/incomplete perimeter	
	Blocked corridor			fence	
G		mounted on top	U	Presence of stray animals	
	of cabinets/shelves			inside the school campus	
G	7 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		Ü	Presence of electrical	
0	Busted plugs/light			post/transformer near or	
	bulbs/electrical facilities		-	within the school perimeter	
	Exposed electrical wires		T.		
		ls in chairs and	·-•	during emergencies	
	tables	•	<b>-</b> i	No posted emergency hotlines around the school	
I	Broken door knobs			Garbage Area (Segregation of	
U	Warning sign:		1.,	Biodegradable and Non-	
<b>.</b>	pathways/com			Biodegradable)	
		d on the building		Detached or peeled off GI sheet	
١,,	railings Flooding		-	Broken toilet bowl and/or sinks	
0	T		0	Broken chairs/desks/tables	
_	Lack/absence of storage for		13	Blocked/no emergency exits	
[ "	equipment		Ω	Unmounted cabinets/shelves	
				Medical kits in every	
·	Dripping ceiling		***	classrooms	
1	Open pit		0	Bells/alarms	
	_ • • • • • • • • • • • • • • • • • • •		t	Condemnable building (i.e. very	
	Unpruned	-		old structure, collapsing	
	trees/bushes/	shrubs		building and/or prominent	
E	Open/Clogged			cracks on classroom walls)	
		elevated school	1.		
-	buildings or of			possible	
9	Swing-in door				
Proposed Actions to be Taken:					
Prepared by:					
School Watching Team  Noted:					
tored:					
School Head					

Þ